

GILFORD WELL COMPANY, INC

1440 LAKE SHORE ROAD
GILFORD, NEW HAMPSHIRE 03249

November 22, 2002

State of New Hampshire
Department of Environmental Services
Water Supply Engineering Bureau
Attn. Alan Leach
6 Hazen Drive, PO Box 95
Concord, NH 03302-0095

RECEIVED

NOV 26 2002

LEGAL UNIT

RE: Letter of Deficiency #WSEB 02-173
Belmont Business Park, EPA # 0206020

Dear Alan,

Gilford Well Company, Inc. is the system operator and sampling agent for the above mentioned system and is looking into the recent occurrences of total coliform within the water system. At this time the system has been chlorinated, recirculated and flushed. There appears to be no leaks within the system. We are looking into the problem and will notify you as to what we find and what has been done to resolve the problem.

If you have any questions or need more information, please give me a call.

Sincerely,

GILFORD WELL COMPANY, INC.

COPY

Norman H. Harris, III
Vice President

cc: Al Mitchell, Belmont Business Park
Gary Boisvert, Health Officer, Town of Belmont
Gretchen Rule, DES Legal Unit
EPA Region 1

NHHIII/te